DG ICFRE Visit to Chitradurga District in Karnataka in connection with Macro EIA study as directed by Hon'ble Supreme Court of India

Dated 7 and 8 October 2011



Dr V K Bahuguna discussing with the officials of MEL mines of Chitradurga



Dr V K Bahuguna assessing the mining impact of Sesa Goa mines of Chitradurga



Dr V K Bahuguna discussing with the officials of MEL mines of Chitradurga



Dr V K Bahuguna discussing with the officials of John mines of Chitradurga



Dr V K Bahuguna inspecting the OB dump of John mines along with EIA team in Chitradurga



Dr V K Bahuguna inspecting the OB dump of John mines along with EIA team in Chitradurga



Dr V K Bahuguna, DG, ICFRE inspecting the Laxmi Narasima mines of Chitradurga



Breaching of OB dump of MEL mines towards forest in Chitradurga



Dr V K Bahuguna, DG, ICFRE discussing the issues with the public along with DC, Chitradurga



Dr V K Bahuguna, DG, ICFRE interacting with the public along with DC, Chitradurga



Dr V K Bahuguna, DG, ICFRE interacting with press at Chitradurga



Dr V K Bahuguna, DG, ICFRE, chaired the meeting with the DC and District officials of Chitradurga




Dr V K Bahuguna, DG, ICFRE, Chairing the meeting with stakeholders of Chtradurga



Dr V K Bhuguna, DG, ICFRE chairing meeting with officials of Chitradurga and DC, Bellary




Dr V K Bhuguna, DG, ICFRE discussing the mining aspects in the meeting with DC,



Dr V K Bhuguna, DG, ICFRE, inspecting and interacting with the officials of MEL mines of Chitradurga



Dr. V K Bahuguna discussing with the officials of Sesa Goa mines and District administration of Chitradurga



Dumping of sub grade ore material just above the mine pit of Laxmi Narasimha mines of Chitradurga



Erosion and improper stacking of fine ore material of Laxmi Narasima mines of Chitradurga



Geo-textile stabilization of steep slopes of OB dump of John mines of Chitradura



Geo-textile stabilization of steep slopes of OB dumps of Sea Goa mines of Chitradurga



Scientific mining pit of Laxmi Narasimha mines of Chitradurga




Sliding of mine benches due to unscientific mining of Sesa Goa mines of Chitradurga



Steep slopes of OB dump of John mines of Chitradurga



Unmanaged and abandoned OB dump of DRR mines, Chitradurga



Unscientific mining of Allum Veerabhadrappa mines of Chitradurga



Unstabilized dump of MEL mines of Chitradurga



Unstabilized steep OB dump sliding towards vegetation of Allum Veerabhadrappa mines, Chitradurga